IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of: Alpert et al. \$ Group Art Unit: 2123 \$ \$ Scrial No.: 09/838,429 \$ Examiner: Craig, Dwin M. \$ Stronger Docket No. A US0200101181

Filed: April 19, 2001 § Attorney Docket No.: AUS920010118US1

For: Practical Methodology for Early Buffer and Wire Resource Allocation

REQUEST FOR CERTIFICATE OF CORRECTION OF OFFICE MISTAKE

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

We would like to request a Certificate of Correction of Office Mistake with regard to issued patent 6.996.512 B2.

There is an error with respect to the following data:

Col. 11, line 29: after "analyzed" delete "(step 1212)" and insert --(step 1214)--.

No fees are believed to be necessary. If, however, any fees are required, I authorize the Commissioner to charge these fees which may be required to Deposit Account No. 09-0447.

Respectfully submitted,

/Peter B. Manzo/
Peter B. Manzo
Registration No. 54,700
Duke W. Yee

Registration No. 34,285 YEE & ASSOCIATES, P.C. P.O. Box 802333 Dallas. Texas 75380

(972) 385-8777

ATTORNEYS FOR APPLICANTS

PTO/SB/44 (04-05)

Approved for use through 04/30/2007. OMB 0851-0035 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number
(Also Form PTO-1059)

MAILING ADDRESS OF SENDER (Please do not use customer number below):

IBM Corporation, IP Law Dept.

11400 Burnet Road

Austin, TX 75758

VA 22313-1450.